


Matrix Report - Extended LEQSE Year 2 - South Hams District Council

	All Areas	Primary Retail/Commercial	Secondary Retail/Commercial	Transport Infrastructure	High Density Housing	Low Density Housing	Low Density Social Housing	Low Density Private Housing	Industry/Warehouse/Retail Sheds	Main Roads	Rural Roads	Other Highways	Public Open Spaces	Watersides
Cleansing Standards														
Litter	Satisfactory	Satisfactory	Satisfactory	Good	Good	Good	Good	Unsatisfactory	Satisfactory	Good	Satisfactory	Good	Good	Good
Detritus	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory
Leaf Fall	Good	Good	Good	Good	Satisfactory	Satisfactory	Good	Good	Good	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Good
Cleansing Related														
Weed Growth	Good	Good	Good	Good	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Good	Good	Satisfactory	Good	Good	Good
Staining	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Good	Good	Good
Flytipping	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Waste Placed Out	Satisfactory	Unsatisfactory	Satisfactory	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Flyposting	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Graffiti	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Highway Infrastructure														
Paved Areas Obstruction	Good	Unsatisfactory	Satisfactory	Satisfactory	Good	Good	Good	Good	Good	Good	Good	Satisfactory	Satisfactory	Satisfactory
Paved Obstruction No Upstand	Poor	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Poor	Poor	Poor	Poor	Poor	Poor	Poor	Poor	Poor
Channel Obstruction	Satisfactory	Unsatisfactory	Satisfactory	Satisfactory	Good	Satisfactory	Good	Satisfactory	Good	Good	Good	Good	Good	Good
Paved Areas Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory
Channel Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Carriageway Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Road Marking Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Poor	Unsatisfactory	Unsatisfactory
Vehicle Flows	Good	Satisfactory	Satisfactory	Good	Good	Good	Good	Good	Unsatisfactory	Good	Good	Good	Good	Good
Pedestrian Flows	Good	Unsatisfactory	Satisfactory	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Street Furniture														
Posts & Poles	Unsatisfactory	Unsatisfactory	Satisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Satisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Public Signs	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Satisfactory	Satisfactory
Other Street Furniture	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Buildings & Boundary Structures	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Litter Bins														
Cleanliness	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory
Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Satisfactory
Degree of Fill	Good	Good	Good	Satisfactory	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good
Bus Stops Etc.														
Litter	Good	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Condition	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Staining	Good	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Flyposting	Good	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Graffiti	Good	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Good	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory	Unsatisfactory
Landscaping														
Litter	Good	Unsatisfactory	Good	Good	Good	Good	Good	Satisfactory	Satisfactory	Good	Satisfactory	Good	Good	Good
Maintenance	Satisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Satisfactory	Satisfactory	Satisfactory	Unsatisfactory	Satisfactory	Unsatisfactory	Unsatisfactory



Footnote: Please see section 1.1.7 in relation to interpreting data at a land use level.